Date	Time	Type	Issue	Method	Detail	Response/Action	Status
15/08/2016	09:00	Complaint	TV Retransmitter	Email-Incoming	Enquiry / Complaint About TV Reception	Directed to wind farm's TV reception contractor	Closed
						to request a home visit.	
06/01/2017	13:10	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
					retransmitter was out of service	to and reset.	
06/01/2017	13:10	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
					retransmitter was out of service	to and reset.	
06/01/2017	13:10	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
					retransmitter was out of service	to and reset.	
06/01/2017	13:10	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
20/24/2017	10.10		T) / D /	4000	retransmitter was out of service	to and reset.	01 1
06/01/2017	13:10	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
20/04/0047	10.10		T) / D /	4000	retransmitter was out of service	to and reset.	01 1
06/01/2017	13:10	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
20/04/0047	10.10		T) / D /	4000	retransmitter was out of service	to and reset.	01 1
06/01/2017	13:10	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
20/04/0047	00.00		T) / D /	4000	retransmitter was out of service	to and reset.	01 1
30/01/2017	00:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
					retransmitter was not broadcasting.	to. Error caused by overnight power outage.	
30/01/2017	21:00	Feedback	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
30/01/2011	21.00	1 Coaback	1 V Trottanomitto	1000	retransmitter was not broadcasting.	to. Error caused by overnight power outage.	0.0000
					retransmitter was not broadcasting.	to. Error caused by overnight power outage.	
14/02/2017	12:00	Enquiry	Other	Email-Incoming	Science student requested permission to visit	Student advised of publicly accessible areas	Closed
11/02/2017	12.00	Liiquiiy	Othor	Linuii incoming	wind farm to take photographs.	suitable for photography.	Ciooca
04/03/2017 18:	18:05	Enquiry	Other	Email-Incoming	Project neighbour previously supplied with	Aerial installation contractor dispatched to	Closed
0 1/ 00/ 20 1 1	10.00	qu)	0		VAST set-top box and satellite dish made	attend and repair.	0.0000
					contact about quality of installation.	attoria aria repairi	
15/03/2017	12:25	Complaint	TV Retransmitter	1800	Issue in Taralga with reception of ABC	Wind Farm Ops Manager advised; techs	Closed
	1				channels only. Checked with ABC - outage	attended retransmitter and reset.	
					from 3-4am 15/3 may have impacted re-		
					transmitter.		
16/03/2017	10:00	Enquiry	Removal of	1800	Neighbour called to enquire about vegetation	Powerline responsibility of Essential Energy.	Open
			Vegetation		clearance around powerline easement on	Currently working with EE on undertaking	
					property.	vegetation management works required.	
16/03/2017	17:00	Complaint	TV Retransmitter	Email-Incoming	Issue in Taralga with reception of ABC	Wind Farm Ops Manager advised; techs	Closed
					channels only. Checked with ABC - outage	attended retransmitter and reset.	
					from 3-4am 15/3 may have impacted re-		
					transmitter.		
16/03/2017	17:00	Complaint	TV Retransmitter	1800	Issue in Taralga with reception of ABC	Wind Farm Ops Manager advised; techs	Closed
					channels only. Checked with ABC - outage	attended retransmitter and reset.	
					from 3-4am 15/3 may have impacted re-		
					transmitter.		
22/03/2017	16:00	Complaint	TV Retransmitter	1800	Issue in Taralga with reception of ABC	Wind Farm Ops Manager advised; techs	Closed
					channels only. Checked with ABC - outage	attended retransmitter and reset.	
					from 3-4am 15/3 may have impacted re-		
20/00/0047	15:45	Compleiet	T\/ Detro:	Empil Internetion	transmitter.	One team orbited TVtransmitter attacks	Closes
	15:45	Complaint	TV Retransmitter	Email-Incoming	Resident in Taralga called to advise the TV retransmitter was out of service	Ops team advised. TV retransmitter attended to and reset.	Closed
29/03/2017				4000	Resident in Taralga called to advise the TV		Closed
	16:40	Complaint					
	16:40	Complaint	TV Retransmitter	1800		Ops team advised. TV retransmitter attended	Cioseu
29/03/2017 29/03/2017	16:40 16:45	Complaint	TV Retransmitter  TV Retransmitter	1800	retransmitter was out of service  Resident in Taralga called to advise the TV  Resident in Taralga called to advise the TV	to and reset.  Ops team advised. TV retransmitter attended to and reset.	Closed

Date	Time	Туре	Issue	Method	Detail	Response/Action	Status
29/03/2017	16:50	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
		-			retransmitter was out of service	to and reset.	
29/03/2017	17:40	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. TV retransmitter attended	Closed
		-			retransmitter was out of service	to and reset.	
07/05/2017	17:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. Fault was caused by	Closed
					retransmitter was out of service	Essential Energy supply fault to TV	
						retransmitter. Restarted itself when power	
						supply restored.	
07/05/2017	17:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. Fault was caused by	Closed
					retransmitter was out of service	Essential Energy supply fault to TV	
						retransmitter. Restarted itself when power	
						supply restored.	
07/05/2017	17:15	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. Fault was caused by	Closed
					retransmitter was out of service	Essential Energy supply fault to TV	
						retransmitter. Restarted itself when power	
						supply restored.	
07/05/2017	18:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. Fault was caused by	Closed
		-			retransmitter was out of service	Essential Energy supply fault to TV	
						retransmitter. Restarted itself when power	
						supply restored.	
07/05/2017	18:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ops team advised. Fault was caused by	Closed
		-			retransmitter was out of service	Essential Energy supply fault to TV	
						retransmitter. Restarted itself when power	
						supply restored.	
16/06/2017	14:30	Enquiry	Communications/Req	Email-Incoming	Request from community renewables	Forwarded to relevant manager for review and	Closed
			uest for information		organisation to interview contractor at wind	approval.	
					farm for video		
24/06/2017	12:05	Complaint	TV Retransmitter	1800		Advised complainant that retransmitter had	Closed
					Resident advised they had returned to the	been commissioned, and that a re-scan would	
					township after an absence of some time, TV	be the best first step. Followed up a few days	
					had stopped working.	later, no further issues or calls recorded.	
0.1/07/00.17	10.05	<u> </u>	1: 5	- "			01 1
24/07/2017	12:35	Enquiry	Sponsorship Request	Email-Incoming	Request for sponsorship	Sponsorship provided	Closed
20/08/2017	8:50	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Wind Farm Ops Manager advised equipment	Closed
					retransmitter was out of service	self-restored	
20/08/2017	9:25	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Wind Farm Ops Manager advised equipment	Closed
		·			retransmitter was out of service	self-restored	
21/08/2017	20:15	Enquiry	Communications/Req	Email-Incoming	Request for information about wind energy for	Response provided	Closed
			uest for information		school project		
29/11/2017	1:00	Complaint	TV Retransmitter	1800	Resident called to advise they had recently	Attempted to contact on details supplied	Closed
		·			started to experience issues with TV signal.	without success on several dates through Dec	
					Provided standard troubleshooting instructions	2017-Feb 2018. Case closed pending further	
					(re-scan) by phone, and asked for details about	contact.	
					antenna configuration. Liaised with Ops team		
					to understand if dwelling received a technician		
					visit and reviewed register of antenna works		
					provided by previous WF owner (no works		
					undertaken at address supplied). Reviewed		
					register and no previous contact from the		
					supplied address.		
							1

Date	Time	Type	Issue	Method	Detail	Response/Action	Status
11/12/2017	14:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Wind Farm Ops Manager advised generator techs present undertaking maintenance, caused temporary outage, restored promptly	Closed
11/12/2017	14:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Wind Farm Ops Manager advised generator techs present undertaking maintenance, caused temporary outage, restored promptly	Closed
24/12/2017	20:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, restored 25/12	Closed
24/12/2017	20:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, restored 25/12	Closed
24/12/2017	20:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, restored 25/12	Closed
24/12/2017	20:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, restored 25/12	Closed
25/12/2017	9:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, restored 25/12	Closed
25/12/2017	9:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, restored 25/12	Closed
25/12/2017	9:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, restored 25/12	Closed
04/01/2018	12:00	Enquiry	Sponsorship Request	Email-Incoming	Community/Environment Group requested sponsorship	Assessed as per guidelines	Closed
30/01/2018	9:00	Enquiry	Sponsorship Request	Email-Incoming	Community/Environment Group requested sponsorship/partnership for greening/landcare program	Assessed as per guidelines and recommended to apply for Community Enhancement Fund	Closed
07/02/2018	11:51	Complaint	TV Retransmitter	1800	Resident in Taralga advised no WIN channels being received	Advised Wind Farm Ops Mgr who contacted service technicians. Fault rectified 7/2	Closed
13/02/2018	9:00	Enquiry	Communications/Req uest for information	Email-incoming	Received request from stakeholder for further information about activities during Taralga bushfires	Information provided	Closed
14/04/2018	15:30	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, Wind Farm Manager attended and restored c.20:00hrs	Closed
14/04/2018	18:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, Wind Farm Manager attended and restored c.20:00hrs	Closed
22/05/2018		Enquiry	Communications/Requ	Email-Incoming	Request for information about diesel consumption	Response provided	Closed
25/05/2018	0:00	Enquiry	Community Fund	Email-Incoming	Request for information about community fund	Response provided	Closed
28/06/2018	14:00	Enquiry	Community Investment	1800	Request for information about community investment	Response provided, process ongoing	Open
29/06/2018	20:30	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	External fault - affected signal from Knight's Hill, Illawarra	Closed
29/06/2018	20:30	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	External fault - affected signal from Knight's Hill, Illawarra	Closed
02/07/2018	0:00	Complaint	TV Retransmitter	1800	Resident advised ongoing issues with television reception - watches free to air television through Foxtel IQ3 box and is located some distance from Taralga township	Ongoing evaluation. Have provided advice to resident to assist	Open
02/07/2018	0:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV retransmitter was out of service	Advised ops, restored same day	Closed

Date	Time	Type	Issue	Method	Detail	Response/Action	Status
02/07/2018	0:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Advised ops, restored same day	Closed
					retransmitter was out of service		
16/07/2018	13:00	Complaint	Other	1800	Resident concerned about public accessing	Monitoring situation and working with	Open
					their private property to take photographs	neighbour to provide durable solution	
19/07/2018	16:00			1800	No details provided		Closed
					•	Case unable to be responded to, closed as a	
						result.	
21/08/2018	16:00	Enquiry	State Government Enq	Email-Incoming	Government freedom of information clearance request	Response provided	Closed
30/08/2018	0:00	Enquiry	Sponsorship Request	Email-Incoming	Request for sponsorship	Request considered	Closed
02/09/2018	0:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ongoing issue that required specialised part.	Closed
		-			retransmitter was experiencing an issue on	Contractors advised. Works completed, called	
					some channels	5/12 and left a voicemail - service restored.	
03/09/2018	0:00	Complaint	TV Retransmitter	1800	Resident in Taralga called to advise the TV	Ongoing issue that required specialised part.	Closed
		-			retransmitter was experiencing an issue on	Contractors advised. Works completed, called	
					some channels	5/12 and left a voicemail - service restored.	
03/09/2018	0:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on	Ongoing issue that required specialised part.	Closed
		-			some channels	Contractors advised. Works completed, called	
						5/12 and left a voicemail - service restored.	
03/09/2018	0:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on	Ongoing issue that required specialised part.	Closed
					some channels	Contractors advised. Works completed, called	
						5/12 and left a voicemail - service restored.	
04/09/2018	0:00	Complaint	TV Retransmitter	Email-Incoming	TV retransmitter was experiencing an issue on	Ongoing issue that required specialised part.	Closed
					some channels	Contractors advised. Works completed, called	
						5/12 and left a voicemail - service restored.	
04/09/2018	0:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on	Ongoing issue that required specialised part.	Closed
					some channels	Contractors advised. Works completed. No	
						details left so unable to return call.	
04/09/2018	0:00	Feedback	TV Retransmitter	1800	TV retransmitter was experiencing an issue on	Ongoing issue that required specialised part.	Closed
					some channels	Contractors advised. Works completed, called	
						5/12 and left a voicemail - service restored.	
04/09/2018	16:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on	Ongoing issue that required specialised part.	Closed
					some channels	Contractors advised. Works completed, called	
						5/12 and left a voicemail - service restored.	
04/09/2018	17:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on	Ongoing issue that required specialised part.	Open
					some channels	Contractors advised. Works completed, called	
						5/12 and left a voicemail - service restored.	
07/09/2018	0:00	Complaint	TV Retransmitter	Telephone-Incom	TV retransmitter was experiencing an issue on	Ongoing issue that required specialised part.	Closed
				,	some channels	Contractors advised. Works completed, called	
						5/12 and left a voicemail - service restored.	

Date	Time	Type	Issue	Method	Detail	Response/Action	Status
07/09/2018	14:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 and left a voicemail - service restored.	Closed
08/09/2018	0:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 and left a voicemail - service restored.	Closed
10/09/2018	0:00	Complaint	TV Retransmitter	Face to Face	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 and left a voicemail - service restored.	Closed
11/09/2018	0:00	Complaint	TV Retransmitter	Face to Face	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 and left a voicemail - service restored.	Closed
11/09/2018	0:00	Complaint	TV Retransmitter	Face to Face	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 and left a voicemail - service restored.	Closed
11/09/2018	0:00	Complaint	TV Retransmitter	Face to Face	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 - service restored.	Closed
11/09/2018	0:00	Complaint	TV Retransmitter	Face to Face	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 - service restored.	Closed
11/09/2018	0:00	Complaint	TV Retransmitter	Face to Face	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 - service restored.	Closed
21/09/2018	0:00	Enquiry	Media Enquiry	1800	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed - service restored.	Closed
28/09/2018	0:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 - service restored.	Closed
04/10/2018	0:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 - service restored.	Closed
11/10/2018	0:00	Complaint	TV Retransmitter	1800	Resident experiencing issue with VAST installation	Requested assistance from contractor, awaiting works	Open
12/11/2018	0:00	Complaint	TV Retransmitter	Email-Incoming	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 - service restored.	Closed
19/11/2018	0:00	Complaint	TV Retransmitter	Email-Incoming	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 - service restored.	Closed
24/11/2018	0:00	Complaint	TV Retransmitter	Email-Incoming	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called 5/12 - service restored.	Closed
09/12/2018	0:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called to advise - service restored.	Closed

Date	Time	Туре	Issue	Method	Detail	Response/Action	Status
09/12/2018	0:00	Feedback	TV Retransmitter	1800	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called to advise - service restored.	Closed
11/12/2018	0:00	Complaint	TV Retransmitter	Email-Incoming	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called to advise - service restored.	Closed
11/12/2018	0:00	Enquiry	TV Retransmitter	1800	TV retransmitter was experiencing an issue on some channels	Contact from broadcast network. Confirmed issue was on TWF equipment.	Closed
12/12/2018	0:00	Complaint	TV Retransmitter	Email-Incoming	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called to advise - service restored Restored 12/12 6pm	Closed
12/12/2018	0:00	Complaint	TV Retransmitter	1800	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called to advise - service restored Restored 12/12 6pm	Closed
12/12/2018	0:00	Complaint	TV Retransmitter	Telephone-Incom	TV retransmitter was experiencing an issue on some channels	Ongoing issue that required specialised part. Contractors advised. Works completed, called to advise - service restored Restored 12/12 6pm	Closed
22/01/2019	0:00	Enquiry	TV Retransmitter	1800	New resident in Taralga, property did not have free to air antenna fitted.	Advised they would need to procure their own antenna, have it installed to access. Provided technical information on how to access TV retransmitter.	Closed
28/01/2019	0:00	Complaint	TV Retransmitter	Email-Incoming	Resident had antenna works conducted at property south of Taralga township. Unable to access retransmitter signal.	Provided technical details for accessing retransmitter signal. Waiting response from resident as to efficacy.	Open
30/01/2019	0:00	Complaint	TV Retransmitter	1800	Resident experiencing issue with VAST installation, request assistance to switch to retransmitter service	Gathered technical advice, working with resident and technician to action	Open